

Docket No.: S1022.81108US00
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE


Applicant: Hilal Ezzeddine et al.
Serial No.: 10/729,682
Confirmation No.: 3164
Filed: December 5, 2003
Patent No.: 7,394,333
For: DIRECTIONAL COUPLER

Examiner: D. O. Takaoka
Art Unit: 2817

Certificate of Electronic Filing Under 37 CFR 1.8

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being transmitted via the Office electronic filing system in accordance with § 1.8(a)(4).

Dated: July 10, 2008


Gail Driscoll

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentees noted a typographical error which should be corrected.

In the Specification:


At column 2, line 22, the terminal identifier "IN" has been changed to read "iN". Terminal identifier "IN" can be found elsewhere in the application. Specifically, terminal identifier IN can be found on page 1, line 12 and on page 2, line 24 as well as on Figs. 1-4.

No amendment was made by either the Examiner or Patentees changing terminal identifier "IN" to "iN". Therefore, the error identified above was not the fault of Patentees, accordingly it is believed that no fee is required. However, should the Examiner determine a fee to be necessary, the fee should be charged to the deposit account of the undersigned, Deposit Account No. 23/2825.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment.
Patentee respectfully solicits the granting of the requested Certificate of Correction.

Dated: July 10, 2008

Respectfully submitted,

By:  _____

James H. Morris
Registration No.: 34,681
WOLF, GREENFIELD & SACKS, P.C.
Federal Reserve Plaza
600 Atlantic Avenue
Boston, Massachusetts 02210-2206
617.646.8000

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,394,333
APPLICATION NO. : 10/729,682
ISSUE DATE : July 1, 2008
INVENTOR(S) : Hilal Ezzeddine et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 2, line 22 should read:
respectively connecting terminals IN and CPLD and ter-

MAILING ADDRESS OF SENDER (Please do not use customer number below):

James H. Morris
WOLF, GREENFIELD & SACKS, P.C.
Federal Reserve Plaza
600 Atlantic Avenue
Boston, Massachusetts 02210-2206

1